


Coil Resistance : 10 Ohms



|                         |                |
|-------------------------|----------------|
| <b>Software Version</b> | V3.1 or Higher |
|-------------------------|----------------|

|                             |      |                    |
|-----------------------------|------|--------------------|
| <b>PWM Output Functions</b> | PWM1 | Idle Speed Control |
|                             | PWM2 | Idle Slave         |

|                                |           |     |
|--------------------------------|-----------|-----|
| <b>Idle Control Parameters</b> | Min Duty  | 0   |
|                                | Max Duty  | 60  |
|                                | Frequency | 200 |

|              |  |                 |            |              |                       |                          |
|--------------|--|-----------------|------------|--------------|-----------------------|--------------------------|
| <b>MoTeC</b> | <b>Title</b> Subaru 3 Wire Idle Valve (M8 ECU) |                 |            |              | <b>Sheet No</b><br>M8 | <b>Drawing No</b><br>V11 |
|              | <b>Date</b> 17/1/1995                          | <b>Drawn</b> TW | <b>App</b> | <b>Rev</b> A |                       |                          |